	Туре	L#	Hits	Search Text
1	BRS	L1	748	rigid near2 interface
2	BRS	L2	44	1 and (bladder)
3	BRS	L3	8	2 and (seat cushion)
4	BRS	L4	154	1 and (bladder chamber)
5	BRS	L5	34	4 and (seat cushion)
6	BRS	L6	43	4 and (vehicle)
7	BRS	L7	9	6 and (seat cushion)
8	BRS	L8	851178	interface
9	BRS	L9	7743	8 and (bladder)
10	BRS	L10	1279	9 and (seat cushion)
11	BRS	L11	1197	10 and (weight load force)
12	BRS	L12	869	11 and (sheet film layer)
13	BRS	L13	169	12 and (mutipl\$5 pair two couple second) near2 (plate)
14	BRS	L14	26	13 and (vehicle)

-	DBs	Time Stamp	Comments	Error Definition	Erro rs
1	USPAT; US-PGPUB; EPO; JPO; DERWENT	2004/06/17 11:45			0
2	USPAT; US-PGPUB; EPO; JPO; DERWENT	2004/06/17 11:45			0
3	USPAT; US-PGPUB; EPO; JPO; DERWENT	2004/06/17 11:46			0
4	USPAT; US-PGPUB; EPO; JPO; DERWENT	2004/06/17 11:44			0
5	USPAT; US-PGPUB; EPO; JPO; DERWENT	2004/06/17 11:44			0
6	USPAT; US-PGPUB; EPO; JPO; DERWENT	2004/06/17 11:47			0
7	USPAT; US-PGPUB; EPO; JPO; DERWENT	2004/06/17 11:44			0
8	USPAT; US-PGPUB; EPO; JPO; DERWENT	2004/06/17 11:45			0
9	USPAT; US-PGPUB; EPO; JPO; DERWENT	2004/06/17 11:45			0
10	USPAT; US-PGPUB; EPO; JPO; DERWENT	2004/06/17 11:46			0
11	USPAT; US-PGPUB; EPO; JPO; DERWENT	2004/06/17 11:46			0
12	USPAT; US-PGPUB; EPO; JPO; DERWENT	2004/06/17 11:46			0
13	USPAT; US-PGPUB; EPO; JPO; DERWENT	2004/06/17 11:47			0
14	USPAT; US-PGPUB; EPO; JPO; DERWENT	2004/06/17 11:47			0

	Туре	L#	Hits	Search Text	DBs
1	BRS	L1	5846	interface near2 panel	USPAT; US-PGPUB; EPO; JPO; DERWENT
2	BRS	L2	67	1 and (bladder)	USPAT; US-PGPUB; EPO; JPO; DERWENT
3	BRS	L3	17	2 and (seat)	USPAT; US-PGPUB; EPO; JPO; DERWENT
4	BRS	L4	374	seat near2 bladder	USPAT; US-PGPUB; EPO; JPO; DERWENT
5	BRS	L5	0	4 and interface near2 panel	USPAT; US-PGPUB; EPO; JPO; DERWENT
6	BRS	L6	11	2 and (vehicle)	USPAT; US-PGPUB; EPO; JPO; DERWENT
7	BRS	L7	18	2 and (seat cushion)	USPAT; US-PGPUB; EPO; JPO; DERWENT
8	BRS	L8	137	73/862.581.ccls.	USPAT; US-PGPUB; EPO; JPO; DERWENT
9	BRS	L9	0	8 and interface near2 panel	USPAT; US-PGPUB; EPO; JPO; DERWENT
10	BRS	L10	0	9 and (bladder)	USPAT; US-PGPUB; EPO; JPO; DERWENT
11	BRS	L12	1	11 and (seat cushion)	USPAT; US-PGPUB; EPO; JPO; DERWENT
12	BRS	L13	2	"6490936"	USPAT; US-PGPUB; EPO; JPO; DERWENT
13	BRS	L14	166640	73/\$9.ccls.	USPAT; US-PGPUB; EPO; JPO; DERWENT
14	BRS	L15	88	14 and interface near2 panel	USPAT; US-PGPUB; EPO; JPO; DERWENT
15	BRS	L17	0	16 and (seat cushion)	USPAT; US-PGPUB; EPO; JPO; DERWENT
16	BRS	L16	3	15 and (bladder)	USPAT; US-PGPUB; EPO; JPO; DERWENT
17	BRS	L18	610	14 and (bladder)	USPAT; US-PGPUB; EPO; JPO; DERWENT
18	BRS	L19	113	18 and (seat cushion)	USPAT; US-PGPUB; EPO; JPO; DERWENT
19	BRS	L20	31	19 and (interface)	USPAT; US-PGPUB; EPO; JPO; DERWENT
20	BRS	L21	25	20 and (weight load force)	USPAT; US-PGPUB; EPO; JPO; DERWENT

	Time Stamp	Comments	Error Definition	Erro rs
1	2004/06/17 11:05			0
2	2004/06/17 11:05			0
3	2004/06/17 11:04			0
4	2004/06/17 11:03			0
5	2004/06/17 11:03			0
6	2004/06/17 11:04			0
7	2004/06/17 11:05			0
8	2004/06/17 11:07			0
9	2004/06/1 <i>7</i> 11:08			0
10	2004/06/1 <i>7</i> 11:08			0
11	2004/06/17 11:42			0
12	2004/06/17 11:06			0
13	2004/06/1 <i>7</i> 11:08			0
14	2004/06/17 11:09			0
15	2004/06/1 <i>7</i> 11:09			0
16	2004/06/1 <i>7</i> 11:09			0
17	2004/06/17 11:32			0
18	2004/06/1 <i>7</i> 11:09			0
19	2004/06/1 <i>7</i> 11:10			0
20	2004/06/17 11:13			0

	Туре	L#	Hits	Search Text	DBs
21	BRS	L22	18	7 and (mass weight load force)	USPAT; US-PGPUB; EPO; JPO; DERWENT
22	BRS	L23	19	"6089106"	USPAT; US-PGPUB; EPO; JPO; DERWENT
23	BRS	L24	32	"6056079"	USPAT; US-PGPUB; EPO; JPO; DERWENT
24	BRS	L26	24	"5957491"	USPAT; US-PGPUB; EPO; JPO; DERWENT
25	BRS	L27	24	"5918696"	USPAT; US-PGPUB; EPO; JPO; DERWENT
26	BRS	L25	4	"6041658"	USPAT; US-PGPUB; EPO; JPO; DERWENT
27	BRS	L28	0	25 and (sheet film layer)	USPAT; US-PGPUB; EPO; JPO; DERWENT
28	BRS	L29	0	25 and (plate)	USPAT; US-PGPUB; EPO; JPO; DERWENT
29	BRS	L30	7	23 and (sheet film layer)	USPAT; US-PGPUB; EPO; JPO; DERWENT
30	BRS	L31	1	30 and (plate)	USPAT; US-PGPUB; EPO; JPO; DERWENT
31	BRS	L32	17	22 and (sheet film layer)	USPAT; US-PGPUB; EPO; JPO; DERWENT
32	BRS	L33	14	24 and (sheet film layer)	USPAT; US-PGPUB; EPO; JPO; DERWENT
33	BRS	L35	11	26 and (sheet film layer)	USPAT; US-PGPUB; EPO; JPO; DERWENT
34	BRS	L37	12	27 and (sheet film layer)	USPAT; US-PGPUB; EPO; JPO; DERWENT
35	BRS	L38	2	37 and (plate)	USPAT; US-PGPUB; EPO; JPO; DERWENT
36	BRS	L36	1	35 and (plate)	USPAT; US-PGPUB; EPO; JPO; DERWENT
37	BRS	L34	5	33 and (plate)	USPAT; US-PGPUB; EPO; JPO; DERWENT
38	BRS	L39	3	34 and (bladder)	USPAT; US-PGPUB; EPO; JPO; DERWENT
39	BRS	L11	5	8 and (bladder)	USPAT; US-PGPUB; EPO; JPO; DERWENT

	Time Stamp	Comments	Error Definition	Erro rs
21	2004/06/17 11:21			0
22	2004/06/17 11:21			0
23	2004/06/17 11:21			0
24	2004/06/17 11:21			0
25	2004/06/17 11:21			0
26	2004/06/17 11:22			0
27	2004/06/17 11:23			0
28	2004/06/17 11:23			0
29	2004/06/17 11:25			0
30	2004/06/17 11:25			0
31	2004/06/17 11:25			0
32	2004/06/17 11:26			0
33	2004/06/17 11:26			0
34	2004/06/17 11:26			0
35	2004/06/17 11:26			0
36	2004/06/17 11:27			0
37	2004/06/17 11:29			0
38	2004/06/17 11:32			0
39	2004/06/17 11:38			0